

1/35




FIG. 1

2/35




FIG. 2

3/35




FIG. 3

4/35





FIG. 4




FIG. 5




FIG. 6

7/35




FIG. 7

8/35




FIG. 8

9/35




FIG. 9

10/35




FIG. 10




FIG. 11A




FIG. 11B




FIG. 12

12/35




FIG. 13

13/35




FIG. 14




FIG. 15A




FIG. 15B

15/35




FIG. 16A

16/35




FIG. 16B

17/35




FIG. 17A

18/35




FIG. 17B




FIG. 18

20/35




FIG. 19




FIG. 20

21/35





FIG. 21A



23/35




FIG. 21C

	N1	Q1	N2	Q2	N3	Q3	N4	Q4
L1	1			17	9			25
L2		22	6			30	14	
L3	11			27	3			19
L4		32	16			24	8	
L5	5			21	13			29
L6		18	2			26	10	
L7	15			31	7			23
L8		28	12			20	4	

FIG. 21D

24/35




FIG. 22A

25/35




FIG. 22B

26/35




FIG. 22C

27/35

	N1	Q1	N2	Q2	N3	Q3	N4	Q4
L1	1		17		9		25	
L2		22		6		30		14
L3	11		27		3		19	
L4		32		16		24		8
L5	5		21		13		29	
L6		18		2		26		10
L7	15		31		7		23	
L8		28		12		20		4

FIG. 22D




FIG. 23A




FIG. 23B




FIG. 23C

30/35

	Q1	Q2	Q3	Q4	Q5	Q6	Q7	Q8
	N1	N2	N3	N4	N5	N6	N7	N8
L1	1	85	25	61	13	73	37	49
L2	72	48	84	12	60	36	96	24
L3	47	71	11	83	35	59	23	95
L4	94	10	70	34	82	22	58	46
L5	9	93	33	69	21	81	45	57
L6	56	32	92	20	68	44	80	8
L7	31	55	19	91	43	67	7	79
L8	78	18	54	42	90	6	66	30
L9	17	77	41	53	5	89	29	65
L10	64	40	76	4	52	28	88	16
L11	39	63	3	75	27	51	15	87
L12	86	2	62	26	74	14	50	38

FIG. 23D




FIG. 24A




FIG. 24B




FIG. 24C

34/35




FIG. 25A




FIG. 25B




FIG. 26